

Belden P/N	Applicable WBT P/N + strain relief ferrule(s) + Heatshrink if needed
9913	WBT-0150 with WBT-0580
8237	WBT-0150 with WBT-0580
8214	WBT-0150 with WBT-0580
9880	WBT-0150 with WBT-0580
9292	WBT-0150 with WBT-0580
7731a-292m	WBT-0150 with WBT-0580
8268	WBT-0150 with WBT-0580
8213	WBT-0150 with WBT-0580
89880	WBT-0150 with WBT-0580
7732a	WBT-0101, WBT-0108, WBT-0110, WBT-0144
7733a	WBT-0101, WBT-0108, WBT-0110, WBT-0144
89292	WBT-0101, WBT-0108, WBT-0110, WBT-0144
8281f	WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580
8281	also WBT-0147 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580
86221	also WBT-0147 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590
9290	also WBT-0147 with WBT-0590 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590
1694a	also WBT-0147 with WBT-0590 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590
9258	also WBT-0147 with WBT-0590 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595
1695a	also WBT-0147 with WBT-0590 + WBT-0595 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595
1505a	also WBT-0147 with WBT-0590 + WBT-0595 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595
9778	also WBT-0147 with WBT-0590 + WBT-0595 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595
9395	also WBT-0147 with WBT-0590 + WBT-0595 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595
9224	also WBT-0147 with WBT-0590 + WBT-0595 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590
9241f	also WBT-0147 with WBT-0590 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590
9259	also WBT-0147 with WBT-0590 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590
1506a	also WBT-0147 with WBT-0590 + WBT-0595 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595
82259	also WBT-0147 with WBT-0590 + WBT-0595 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595
9273	also WBT-0147 with WBT-0590 + WBT-0595 WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595
9394	also WBT-0147 with WBT-0590 + WBT-0595 + 3/8" B2 Heatshrink WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595 + 3/8" B2 Heatshrink
89259	also WBT-0147 with WBT-0590 + WBT-0595 + 3/8" B2 Heatshrink WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595 + 3/8" B2 Heatshrink
16730	also WBT-0147 with WBT-0590 + WBT-0595 + 1/4" B2 Heatshrink WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595 + 1/4" B2 Heatshrink
9223	also WBT-0147 with WBT-0590 + WBT-0595 + 1/4" B2 Heatshrink WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595 + 3/8" B2 Heatshrink
1865a	also WBT-0147 with WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink
1855a	also WBT-0147 with WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink
8218	also WBT-0147 with WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink
9456	also WBT-0147 with WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink WBT-0101, WBT-0108, WBT-0110, WBT-0144 with WBT-0580 + WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink
16710	WBT-0147 with WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink
16720	WBT-0147 with WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink
8417	WBT-0147 with WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink
8411	WBT-0147 with WBT-0590 + WBT-0595 + 1/4" W5E Heatshrink
9239	WBT-0147 with WBT-0590 + WBT-0595 + 1/8" W5DL Heatshrink
8216	WBT-0147 with WBT-0590 + WBT-0595 + 1/8" W5DL Heatshrink
8416	WBT-0147 with WBT-0590 + WBT-0595 + 1/8" W5DL Heatshrink